

## REPORT OF A THOROUGH EXAMINATION OF LIFTING EQUIPMENT

In accordance with the Lifting Operations & Lifting Equipment Regulations 1998 (LOLER)

Name of client or contact
Lite Alternative Ltd Unit 4 Duttons Way Shadsworth Business Park Blackburn BB1 2QR

Location of test or inspection:
Lite Alternative Ltd Unit 4 Duttons Way Shadsworth Business Park Blackburn BB1 2QR

<b>Date of last inspection:</b>	28/08/2018
<b>Date of thorough examination:</b>	21/08/2019
<b>Next through examination due:</b>	21/08/2020

<b>Examination period</b>	Within an interval of 12 months
<b>Record number</b>	JR73482
<b>Colour code:</b>	Yellow

Equipment details:					
<b>Serial (Fleet) #</b>	A05622	<b>HoL</b>	17m	<b>Connector</b>	Harting 16 pin
<b>Make/Model</b>	Liftket Type:SB4.2/10m (Kinesys)	<b>Chain ID#</b>	(RUD) S16 / 008	<b>Speed</b>	10mpm
<b>SWL</b>	1000kg	<b>Chain falls</b>	1	<b>Duty cycle</b>	25%
<b>Date of man.</b>	2010	<b>Chain stop</b>	YES	<b>FEM Group</b>	1Bm
<b>Category</b>	BGV-D8	<b>Chainbag</b>	Single point	<b>Brake</b>	DC (double)
<b>Suspension</b>	Eye	<b>(v/ph/Hz)</b>	415/3/50	<b>Control</b>	Low voltage

Report:	
Details of inspection carried out:	Thorough external and internal visual inspection
Details of test carried out:	Proof load test of 1250kg
Reportable defects (If none, state none):	NONE
Is this a defect which is of immediate danger to persons? (Y/N):	N
Is this a defect which is not yet, but could become a danger to persons? (Y/N):	N
Details of any repairs carried out:	
Is this equipment safe to operate?	Yes
Additional comments:	

Signature  (Alun Jones)

Signature  (Ben Dawson)

*We hereby certify that the unit stated has been Tested or Inspected and confirms to the manufacturers specifications.  
In the case of any modification of the equipment which has not been agreed upon with us in writing, this certificate becomes invalid.*