

REPORT OF A THOROUGH EXAMINATION OF LIFTING EQUIPMENT

In accordance with the Lifting Operations & Lifting Equipment Regulations 1998 (LOLER)

Name of client or contact
Lite Alternative Ltd Unit 4 Duttons Way Shadsworth Business Park Blackburn BB1 2QR

Location of test or inspection:
Just Rigging & Inspections Ltd. Unit 3 - Ketlan Court River Lane Saltney Chester CH4 8SB

Date of last inspection:	28/08/2018
Date of thorough examination:	19/08/2019
Next through examination due:	19/08/2020

Examination period	Within an interval of 12 months
Record number	JR73296
Colour code:	Yellow

Equipment details:					
Serial (Fleet) #	11491-20	HoL	25m	Connector	Cee form 4 pin
Make/Model	LoadGuard LG20/1/4/D8P	Chain ID#	RTS 004	Speed	4mpm
SWL	1000kg	Chain falls	1	Duty cycle	40%
Date of man.	2015	Chain stop	YES	FEM Group	M5
Category	BGV-D8+	Chainbag	Twin point	Brake	DC (double)
Suspension	Swivel hook	(v/ph/Hz)	400/3/50	Control	Low volt.

Report:	
Details of inspection carried out:	Thorough external and internal visual inspection
Details of test carried out:	Proof load test of 1250kg
Reportable defects (If none, state none):	NONE
Is this a defect which is of immediate danger to persons? (Y/N):	N
Is this a defect which is not yet, but could become a danger to persons? (Y/N):	N
Details of any repairs carried out:	
Is this equipment safe to operate?	Yes
Additional comments:	Hour count - 14(01)

Signature  (Alun Jones)

Signature  (Ben Dawson)

*We hereby certify that the unit stated has been Tested or Inspected and confirms to the manufacturers specifications.
In the case of any modification of the equipment which has not been agreed upon with us in writing, this certificate becomes invalid.*

REPORT OF A THOROUGH EXAMINATION OF LIFTING EQUIPMENT

In accordance with the Lifting Operations & Lifting Equipment Regulations 1998 (LOLER)

Name of client or contact
Lite Alternative Ltd Unit 4 Duttons Way Shadsworth Business Park Blackburn BB1 2QR

Location of test or inspection:
Just Rigging & Inspections Ltd. Unit 3 - Ketlan Court River Lane Saltney Chester CH4 8SB

Date of last inspection:	10/04/2018
Date of thorough examination:	09/04/2019
Next through examination due:	09/04/2020

Examination period	Within an interval of 12 months
Record number	JR58319
Colour code:	Purple

Equipment details:					
Serial (Fleet) #	11492-20	HoL	25m	Connector	Cee form 4 pin
Make/Model	LoadGuard LG20/1/4/D8P	Chain ID#	(RUD) A55 / 004	Speed	4mpm
SWL	1000kg	Chain falls	1	Duty cycle	40%
Date of man.	2015	Chain stop	YES	FEM Group	M5
Category	BGV-D8+	Chainbag	Twin point	Brake	DC (double)
Suspension	Swivel hook	(v/ph/Hz)	400/3/50	Control	Low voltage

Report:	
Details of inspection carried out:	Thorough external and internal visual inspection
Details of test carried out:	Proof load test of 1250kg
Reportable defects (If none, state none):	NONE
Is this a defect which is of immediate danger to persons? (Y/N):	N
Is this a defect which is not yet, but could become a danger to persons? (Y/N):	N
Details of any repairs carried out:	
Is this equipment safe to operate?	Yes
Additional comments:	Hr count: 00011

Signature  (Alun Jones)

Signature  (Ben Dawson)

Signature  (James Dickinson)

*We hereby certify that the unit stated has been Tested or Inspected and confirms to the manufacturers specifications.
In the case of any modification of the equipment which has not been agreed upon with us in writing, this certificate becomes invalid.*

REPORT OF A THOROUGH EXAMINATION OF LIFTING EQUIPMENT

In accordance with the Lifting Operations & Lifting Equipment Regulations 1998 (LOLER)

Name of client or contact
Lite Alternative Ltd Unit 4 Duttons Way Shadsworth Business Park Blackburn BB1 2QR

Location of test or inspection:
Just Rigging & Inspections Ltd. Unit 3 - Ketlan Court River Lane Saltney Chester CH4 8SB

Date of last inspection:	10/04/2018
Date of thorough examination:	09/04/2019
Next through examination due:	09/04/2020

Examination period	Within an interval of 12 months
Record number	JR58320
Colour code:	Purple

Equipment details:					
Serial (Fleet) #	11493-20	HoL	25m	Connector	Cee form 4 pin
Make/Model	LoadGuard LG20/1/4/D8P	Chain ID#	(RUD) A55 / 005	Speed	4mpm
SWL	1000kg	Chain falls	1	Duty cycle	40%
Date of man.	2015	Chain stop	YES	FEM Group	M5
Category	BGV-D8+	Chainbag	Twin point	Brake	DC (double)
Suspension	Swivel hook	(v/ph/Hz)	400/3/50	Control	Low voltage

Report:	
Details of inspection carried out:	Thorough external and internal visual inspection
Details of test carried out:	Proof load test of 1250kg
Reportable defects (If none, state none):	NONE
Is this a defect which is of immediate danger to persons? (Y/N):	N
Is this a defect which is not yet, but could become a danger to persons? (Y/N):	N
Details of any repairs carried out:	
Is this equipment safe to operate?	Yes
Additional comments:	Hr count: 00012

Signature  (Alun Jones)

Signature  (Ben Dawson)

Signature  (James Dickinson)

*We hereby certify that the unit stated has been Tested or Inspected and confirms to the manufacturers specifications.
In the case of any modification of the equipment which has not been agreed upon with us in writing, this certificate becomes invalid.*