

REPORT OF A THOROUGH EXAMINATION OF LIFTING EQUIPMENT

In accordance with the Lifting Operations & Lifting Equipment Regulations 1998 (LOLER)

Name of client or contact
Lite Alternative Ltd Unit 4 Duttons Way Shadsworth Business Park Blackburn BB1 2QR

Location of test or inspection:
Just Rigging & Inspections Ltd. Unit 3 - Ketlan Court River Lane Saltney Chester CH4 8SB

Date of last inspection:	16/02/2018
Date of thorough examination:	12/12/2018
Next through examination due:	12/12/2019

Examination period	Within an interval of 12 months
Record number	JR40270
Colour code:	Orange

Equipment details:					
Serial (Fleet) #	D03588	HoL	20m	Connector	Harting 16 pin
Make/Model	Liftket Type:SB4.2/14m (Kinesys)	Chain ID#	(RUD) F80 / 003	Speed	20mpm
SWL	500kg	Chain falls	1	Duty cycle	25%
Date of man.	2013	Chain stop	YES	FEM Group	1Bm
Category	BGV-D8	Chainbag	Single point	Brake	DC (double)
Suspension	Eye	(v/ph/Hz)	415/3/50	Control	Low voltage

Report:	
Details of inspection carried out:	Thorough external and internal visual inspection
Details of test carried out:	Proof load test of 625kg
Reportable defects (If none, state none):	chain bag is torn, replace before next use.
Is this a defect which is of immediate danger to persons? (Y/N):	N
Is this a defect which is not yet, but could become a danger to persons? (Y/N):	N
Details of any repairs carried out:	
Is this equipment safe to operate?	Yes
Additional comments:	

Signature  (Alun Jones)

Signature  (Neil Carney)

*We hereby certify that the unit stated has been Tested or Inspected and confirms to the manufacturers specifications.
In the case of any modification of the equipment which has not been agreed upon with us in writing, this certificate becomes invalid.*