

REPORT OF A THOROUGH EXAMINATION OF LIFTING EQUIPMENT

In accordance with the Lifting Operations Lifting Equipment Regulations 1998 (LOLER)

Name of client or contact:	
Lite Alternative Ltd	
Unit 4, Duttons Way	
Shadsworth Business Park	
Blackburn	
BB1 2QR	

Location of test or inspection	
Just Rigging & Inspections workshop - Chester	

Date of test or inspection:	21/12/2016
Next test or inspection due date:	21/12/2017
Test or inspection period (6/12 months)	12 months
Date of last test:	16/09/2014

Test or inspection report number:	JR&IL 367
Colour code:	Purple
Page number:	022
Date of this report:	21/12/2016


Equipment Details:		Description of Equipment:
ID Mark:	BS10504	Manual chain hoist 8 metre HOL on a single chain Single point chain bag fitted Chain ID: H1
Quantity:	1	
SWL:	500 Kg	
Date Manufactured:	2010	
Category:	Manual chain hoist	
Load Test:	Yes	
Inspection:	Thorough Examination	

Report:	
Details of inspection carried out:	Thorough external visual inspection
Details of test carried out:	Load Test of 625 Kg
Reportable defects (If none, state none):	None
Is this a defect which is of immediate danger to persons?	
Is this a defect which is not yet, but could become a danger to persons? Y/N	
Details of any repairs carried out:	N/A
Is this equipment safe to operate?	Yes
Additional comments:	N/A

Name of the person making this report:

Lisa Rhymer

Name & signature of person authenticating this report:

 (Dan Holme)

We hereby certify that the unit stated has been Tested or Inspected and conforms to the manufacturers specifications.

In the case of any modification of the equipment which has not been agreed upon with us in writing, this certificate becomes invalid.