

REPORT OF A THOROUGH EXAMINATION OF LIFTING EQUIPMENT

In accordance with the Lifting Operations Lifting Equipment Regulations 1998 (LOLER)

Name of client or contact:	
Lite Alternative Ltd Unit 4, Duttons Way Shadsworth Business Park Blackburn BB1 2QR	

Location of test or inspection	
Just Rigging & Inspections Ltd Store	


Date of test or inspection:	16/09/2014
Next test or inspection due date:	16/09/2015
Test or inspection period (6/12 months)	12 months
Date of last test:	Unknown

Test or inspection report number:	JR&IL 115
Colour code:	Green
Page number:	003
Date of this report:	30/09/2014

Equipment Details:		Description of Equipment:
ID Mark:	BS10505	Manual chain hoist 8 metre HOL on a single chain Single point chain bag fitted Manual pulling power
Quantity:	1	
SWL:	500 Kg	
Date Manufactured:	2010	
Category:	Manual Chain Hoist	
Load Test:	Yes	
Inspection:	Thorough Examination	

Report:	
Particulars of any test or inspection carried out:	Dynamic Load Test - 500 Kg
Details of test or inspection carried out:	Proof Load Test - 625 Kg
Reportable defects (If none, state none):	N/A
Is this a defect which is of immediate danger to persons?	
Is this a defect which is not yet, but could become a danger to persons? Y/N	N/A
Details of any repairs carried out:	
Is this equipment safe to operate?	Yes
Additional comments:	Damaged chain near hook. Cut down to 8 metres HOL from 10 metres HOL. Agreed by Jon Greaves.

Name of the person making this report:
Lisa Rhymer

Name & signature of person authenticating this report:
 (Dan Holme)

*We hereby certify that the unit stated has been Tested or Inspected and conforms to the manufacturers specifications.
In the case of any modification of the equipment which has not been agreed upon with us in writing, this certificate becomes invalid.*