

## REPORT OF A THOROUGH EXAMINATION OF LIFTING EQUIPMENT

In accordance with the Lifting Operations Lifting Equipment Regulations 1998 (LOLER)

Name of client or contact:	
Lite Alternative Ltd	
Unit 4, Duttons Way	
Shadsworth Business Park	
Blackburn	
BB1 2QR	

Location of test or inspection	
Just Rigging & Inspections workshop - Chester	

Date of test or inspection:	21/12/2016
Next test or inspection due date:	21/12/2017
Test or inspection period (6/12 months)	12 months
Date of last test:	16/09/2014

Test or inspection report number:	JR&IL 367
Colour code:	Purple
Page number:	023
Date of this report:	21/12/2016


Equipment Details:		Description of Equipment:
ID Mark:	BS10565	<b>Manual chain hoist</b> 10 metre HOL on a single chain Single point chain bag fitted Chain ID: H1
Quantity:	1	
SWL:	500 Kg	
Date Manufactured:	2010	
Category:	Manual chain hoist	
Load Test:	Yes	
Inspection:	Thorough Examination	

Report:	
Details of inspection carried out:	Thorough external visual inspection
Details of test carried out:	Load Test of 625 Kg
Reportable defects (If none, state none):	None
Is this a defect which is of immediate danger to persons?	
Is this a defect which is not yet, but could become a danger to persons? Y/N	
Details of any repairs carried out:	N/A
Is this equipment safe to operate?	Yes
Additional comments:	N/A

Name of the person making this report:

Lisa Rhymer

Name & signature of person authenticating this report:

 (Dan Holme)

*We hereby certify that the unit stated has been Tested or Inspected and conforms to the manufacturers specifications.*

*In the case of any modification of the equipment which has not been agreed upon with us in writing, this certificate becomes invalid.*

Just Rigging & Inspections Ltd, Unit 3 Ketlan Court, River Lane, Saltney, Chester, CH4 8SB.

Tel: +44(0)7737939124, E-Mail: enquiries@justrigging.co.uk, Web: www.justrigging.co.uk