

REPORT OF A THOROUGH EXAMINATION OF LIFTING EQUIPMENT

In accordance with the Lifting Operations Lifting Equipment Regulations 1998 (LOLER)

| Name of client or contact: | |
|----------------------------|--|
| Lite Alternative Ltd | |
| Unit 4, Duttons Way | |
| Shadsworth Business Park | |
| Blackburn | |
| BB1 2QR | |

| Location of test or inspection | |
|---|--|
| Just Rigging & Inspections workshop - Chester | |

| | |
|---|------------|
| Date of test or inspection: | 12/02/2016 |
| Next test or inspection due date: | 12/02/2017 |
| Test or inspection period (6/12 months) | 12 months |
| Date of last test: | 19/03/2015 |

| | |
|-----------------------------------|------------|
| Test or inspection report number: | JR&IL 251 |
| Colour code: | Orange |
| Page number: | 003 |
| Date of this report: | 15/02/2016 |


| Equipment Details: | | Description of Equipment: |
|--------------------|----------------------|---|
| ID Mark: | L-4457 TE | CM Lodestar (Model F) electric entertainment hoist Lifting capacity: 500 Kg on one chain fall. Lifting speed: 4m/min. Lifting height: 22 metres. Chain bag: twin point. Chain ID: (RUD) V09/005. Power supply: 415V - 3 Ph - 50Hz ± 10%. Duty factor: 50%, 300 starts p/h. Control: low voltage. Power connectors: 4 pin Cee form. Upright & inverted working. Limit switch: set. Dead Stop: no. Swivel hook suspension. |
| Quantity: | 1 | |
| SWL: | 500 Kg | |
| Date Manufactured: | May-08 | |
| Category: | BGV-D8 | |
| Load Test: | Yes | |
| Inspection: | Thorough Examination | |

| Report: | |
|--|--|
| Details of inspection carried out: | Thorough external and internal visual inspection |
| Details of test carried out: | Load Test of 625 Kg |
| Reportable defects (If none, state none): | Back frame cover badly cracked |
| Is this a defect which is of immediate danger to persons? | No |
| Is this a defect which is not yet, but could become a danger to persons? Y/N | No |
| Details of any repairs carried out: | N/A |
| Is this equipment safe to operate? | Yes |
| Additional comments: | Advise replacing back frame cover. Brake mounting bolts loose - tightened. |

Name of the person making this report:

Lisa Rhymer

Name & signature of person authenticating this report:

 (Dan Holme)

We hereby certify that the unit stated has been Tested or Inspected and conforms to the manufacturers specifications.

In the case of any modification of the equipment which has not been agreed upon with us in writing, this certificate becomes invalid.

Just Rigging & Inspections Ltd, Unit 3 Ketlan Court, River Lane, Saltney, Chester, CH4 8SB.

Tel: +44(0)7737939124, E-Mail: enquiries@justrigging.co.uk, Web: www.justrigging.co.uk